

# FILE NOTATIONS

Entered in NID File

Entered On S R Sheet

Location Map Pinned

Card Indexed

IWR for State or Fee Land

*[Signature]*

Checked by Chief

Copy NID to Field Office

Approval Letter

Disapproval Letter

## COMPLETION DATA:

Date Well Completed

Location Inspected

OW..... WW..... TA.....

Bond released

GW..... OS..... PA ☒

State of Fee Land

## LOGS FILED

Driller's Log

*[Signature]*

Electric Logs (No. )

E..... I..... E-I..... GR..... GR-N..... Micro.....

Lat..... Mi-L..... Sonic..... Others.....

0		
15		

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office SIC  
Lease No. 067596-A  
Unit \_\_\_\_\_

7/1/58  
8-11-58

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 24, 1958, 19

Cedar Mesa Unit

Well No. 1 is located 660 ft. from N line and 1905 ft. from W line of sec. 15

NW/4 Section 15

39S

18E

SIM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Cedar Mesa WC

San Juan

Utah

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft. 6700' GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well plugged and abandoned as follows: Placed cement plugs - 40 sacks 3140-3040'; 40 sacks 2440-2340'; 25 sacks 2240-2180'; 40 sacks 860-760'; 15 sacks in top of hole, erected a 4" dry hole marker extending 4' above ground ~~low~~ level, filled pits and cleaned location. - Ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Carter Oil Company

Production Department

Address Box 3082

Durango, Colorado

COPY (ORIGINAL SIGNED) H. L. FARRIS

By H L Farris

Title District Foreman